CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or reveiation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

				25X1A
COUNTRY	East Germany		REPORT NO.	
SUBJECT	Sabotage of	the SOVEESKI SOYUZ at the	DATE DISTR.	30 December 1953
	Warnow-Werft	, Wartie muende	NO. OF PAGES	1
DATE OF IN	NFO.	25X1A	REQUIREMENT NO.	25X1A
PLACE ACQ	UIRED	20/(1/(REFERENCES	
Ph Mg.			5).
	тн 25X1X	E SOURCE EVALUATIONS IN THIS REPORT THE APPRAISAL OF CONTENT IS T (FOR KEY SEE REVERSE)	RE DEFINITIVE.	<u> </u>
	100	Volkspolizist Heinz Wac		
	Other than three	other guards, the only post	engine room of the sons on board the s ime to be used as l	cave during the
2.	time were a special strategy strategy for the list increased he was back at his room was under wat from the starboard of the pipe system engine room and the was discovered, it flow of water. It is estimated the and pump out the transport of the property	other guards, the only positive of the crew accruing overti. Wack left the ship and, covered that the ship was after some time to a maximater some time to a maximate. Approximately 400 ton anti-roll tanks but, becan, the water did not flow on the lower portions of the human at 8 to 14 days work will water from the hull.	ime to be used as liveturning after an listing 10 degrees mum of 12 degrees. In had been alerted as of water had been use of a prior removation the ship but all. By the time the emergency valves the required to repair the company of the required to repair the samage, regular voltages and the samage, regular voltages are postock and	eave during the unspecified to starboard. By the time and the engine a released wal of part of flooded the ais to stop the air the damage as spolized all entrances
2.	time were a special control of the pipe system and the was back at his from the starboard of the pipe system engine room and the was discovered, it flow of water. It is estimated the and pump out the time the starboard of the pipe system engine room and the was discovered, it flow of water. It is estimated the and pump out the time distely followed the system of	other guards, the only pool of the crew accruing overting over the wark left the ship and, covered that the ship was after some time to a maximater some time to a maximater. Approximately 400 ton anti-roll tanks but, becan, the water did not flow one lower portions of the hut was impossible to use the mat 8 to 14 days work will water from the hull.	ime to be used as liveturning after an listing 10 degrees mum of 12 degrees. In had been alerted as of water had been use of a prior removation the ship but all. By the time the emergency valves the required to repair the company of the required to repair the samage, regular voltages and the samage, regular voltages are postock and	eave during the unspecified to starboard. By the time and the engine released val of part flooded the sis to stop the air the damage kspolizei all entrances

SECRET

STATE	T	ARMY	-	NAVY	x	AIR	ж	FBI		AEC			<u> </u>	
STATE	X	AMIT.	1.4		1									- 1
		Anne		I For Pal	0760	2002/07	77a -	מחם_אויז	<u>80_0</u>	081000	320	0550002	_1	